

Report of Discharge	(CSO\SSO\RTB)
---------------------	---------------

Report of Discharge	arge (CSU\SSI	D(KIB)			
Submission HNX-R2QS	-MDKKS Revision	2 Form Version	n 1.10		
	rekastus välit vuonna tala tamana assa täätään säälä kästä täi vaitata telettäänen en että tai tala tala tala t	ann airthe ann ain an Air Airthean (airthean airthean an Airthean an Airthean Airthean Airthean Airthean Airth	militaria (m. 1944). A series de la completa de la	, and annihilation with the control of the control	
Review					
This step allows you to revisubmission.	ew the form to confirm th	he form is populated (completely and accurat	ely, prior to certification an	d
REPORT DETAILS					
Is this the inital or final of Final	discharge report?				
Site/Facility Name: Lake Mitchell Sewer Au	uthority (former Wexfo	ord Co DPW) CM	and described and described in the control of the c		

Permit Number (if applicable):

None Specified

Sewer System Owner

Is the outfall or discharge area le NO	ocated at a private re	sidential addres	ss?	
Outfall Name Grinder Pump Station 53	A			was an annua annua ana an annua annua an an annua an annua an
Outfall Description Broken Discharge line on	grinder pump s		and the second s	ermanne konkretiket i tristigende Promoter (Priestrie Priestrie Art.)
Outfall Location		-0.000 000 000 000 000 000 000 000 000 0	ggern Allinger i Lindon (Veronaus i villo)	gggreen commence of the section of t
Latitude 44.25979999999999	Longitude -85.4974957			
Has the discharge ended? YES		e de la companya de l	en e	consistency and consistency consistency and an extensive section () If it is also in () is a set of the consistency and consistency are consistency and consistency and consistency are consistency and consistency and consistency are consistency and consistency are consistency and consistency and consistency are consistency and consistency are consistency and consistency are cons
Volume Discha	raed	Unit	COLORADO COMO SERVICIO SERVICIO COMO CONTRACTORIO CONTRAC	Was the volume estimated?
600	. 3	Gallons	Yes	
				A 10A 10A 10 10 10 10 10 10 10 10 10 10 10 10 10
Quality of Discharge Raw Sewage				
Please describe the discharge, in On 2/22/20 at 11:30 a.m. to 110 Birch Court, GPS 5 arrival, the Technician observed indicated a possible alarming due to a tripped. When the Technician resobserved the ground adjawas immediately shut do the station were contacted that would drain into the LMSA's emergency crewidiscovered a cracked discompleted at approximate was the land or surface water in Land impacted only	an LMSA Sewe 3A, to respond to served sand covole break in the did breaker that accept to the wet own. The resident sewer system uses onsite at apcharge line and tely 4:15 a.m.	r Technician to an emerge vering the lice ischarge line tivated the h nd activated well begin to ts with home refrain from intil the repa pproximately the repair w	ency alarm I of the wei es. The stat high water the pumps o perk. The es connect using anyt ir was com / 2:30. The	. Upon t well, tion was alarm. s, he estation ed to ching npleted.
Name/description of the land im Grinder Pump Station 53	ipacted: BA - 110 Birch Cc	ourt		words, to allocations among contactions, commissions, see
Discharge Event Start	Marie III (1997) (Marie Indonésia (1998) (Marie Indoné			was also accounted the communication of the deficiency of the control of the cont
	Date		egypegloth on a second of the second of the second	Time
2/22/2020				11:25 AM

Discharge Event End

Date Time 2/22/2020 12:00 PM

Name of the wastewater treatment facility that normally receives sewage.

Cadilla Wastewater Treatment Plant

Was the reported discharge caused by a party other than the sewer system owner and out of the control or knowledge of the actions which resulted in the discharge?

NO

is the sewer system owner in compliance with applicable discharge permits, laws, rules, and orders?

YES

Initial Notification

Organization	Date	Time	
Local Health Department	2/23/2020	9:37 AM	
Daily Local Newspaper	2/23/2020	9:37 AM	

Notification that discharge has concluded.

Organization	Date	Time	
Local Health Department	2/23/2020	9:37 AM	
Daily Local Newspaper	2/23/2020	9:37 AM	

Precipitation Type(s) (Select none if there was no precipitation)

None

Actions taken to minimize the impact from the discharge(s):

The grinder pump station was immediately shut down. Staff contacted the homeowners that are connected to the GPS and asked them to discontinue use of the sewer system until the repair was made. LMSA had an emergency repair crew onsite within a couple of hours to excavate the area to make the repair. The soil was removed and replaced with new soil.

Actions taken, or that will be taken, to prevent this discharge event from reoccurring:
The SSO was from a broken discharge line that is approximately 43
years old. LMSA is in the process of obtaining an RD loan to replace the aging discharge lines.

ADDITIONAL DETAILS

Report Submitter

Contact Auto-fill

None Specified

Prefix

First Name

Last Name

None Specified

Sheila

Hill

Title

Project Manager

Organization Name

Lake Mitchell Sewer Authority

Phone Type

Phone Number

Ext.

Business

2317750155

None Specified

Email

operationsoffice@lakemitchellsewer.com

Fax

2317750156

3161 South Lake Mitchell Drive

Cadillac

MΙ

49601

US

Do you have any additional comments or uploads you would like to provide? $\ensuremath{\mathsf{YES}}$

Additional Information

None Specified

Upload addition information, as needed.

Feb 22 2020 53A.jpeg

Repaired Discharge Line Feb 23 2020.jpeg

Comment

None Specified