Table of Contents

Table of Contents Report of Discharge (CSO\SSO\RTB)		
(Submission #: HPA-XNCJ-M5S65, version 1)		
Details		
Form Input		
Report Details		
Discharge Details (1 of 1)		
SSO Discharge from SPS 1B located at 1754 East Lake Mitchell Drive		
Additional Details		
Status History		4

8/16/2021 4:05:35 PM Page 1 of 5

Report of Discharge (CSO\SSO\RTB)

version 1.14

(Submission #: HPA-XNCJ-M5S65, version 1)

Details

Submission ID HPA-XNCJ-M5S65

Status

Submitted

Form Input

Report Details

Is this the inital or final discharge report?

Initial

Site/Facility Name:

Lake Mitchell Sewer Authority (former Wexford Co DPW) CM

Permit Number (if applicable):

NONE PROVIDED

Sewer System or Treatment Facility Owner

Organization Name

Lake Mitchell Sewer Authority

Phone Type Number Extension

Business 2317750155

Email

operationsoffice@lakemitchellsewer.com

Fax

2317750156

Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

United States

Facility Address

3161 South Lake Mitchell Drive

Cadillac, MI 49601

Sewer System or Treatment Facility Owner Location

44.2298,-85.5088

3161 South Lake Mitchell Drive, Cadillac, MI

Discharge Details (1 of 1)

SSO Discharge from SPS 1B located at 1754 East Lake Mitchell Drive

8/16/2021 4:05:35 PM Page 2 of 5

Discharge Type:

SSO Discharge

SSO Discharge

The reported discharge is from a private or municipal separate sewer collection system (not a wastewater treatment plant) during wet or dry weather, or a dry weather discharge from a municipal combined sewer collection system.

Is the outfall or discharge area located at a private residential address?

NO

Outfall or Discharge Area Name

SPS 1B located at 1754 East Lake Mitchell Drive

Outfall or Discharge Area Description

SPS cement pad and adjacent grassland and swamp directly east of the station

Outfall or Discharge Area Location

44.2592838,-85.4688096

Has the discharge ended?

YES

Volume Discharged	Unit	Was the volume estimated?
2500	Gallons	Yes

Quality of Discharge

Raw Sewage

Please describe the discharge, including the reason for Discharge

At approximately 7:40p.m., lift station 1B, that is located on East Lake Mitchell Drive experienced a sewer overflow. This was due to the surge of sewer flow after the power was restored to the upstream grinder and lift pump stations. The lift station intermittently discharged until 8:25p.m. There was potential impact to the wetlands located directly east of the station.

Was the land or surface water impacted by the discharge?

Both land and water impacted

Name of Surface Water(s) Impacted:		
Wetlands dire	ctly east of the lift station	

Name/description of the land impacted:

Lift station cement pad, adjacent ground, side of the road, and wetlands (swamp) directly east of the station

Discharge Event Start

Date	Time	
8/11/2021	07:37 pm	

Discharge Event End

Date Date	Time
08/11/2021	08:25 pm

Initial Notification

Organization	Date	Time
Local Health Department	08/11/2021	09:43 pm
Daily Local Newspaper	08/11/2021	09:43 pm

Was EGLE notified prior to this report being received?

EGLE was notified prior to this report being submitted

Prior EGLE notification that discharge has started

8/16/2021 4:05:35 PM Page 3 of 5

EGLE Notification Method	Person(s) notified	EGLE Notification Date	EGLE Notification Time	Comments
Phone	Donal Brady	08/11/2021	08:41 pm	NONE PROVIDED

Notification that discharge has concluded.

Organization	Date	Time
Local Health Department	08/11/2021	09:43 pm
Daily Local Newspaper	08/11/2021	09:43 pm

Precipitation Type(s) (Select none if there was no precipitation)

None

Was this discharge disinfected to meet fecal coliform limitations?

NO

Additional Details

Report Submitter

Prefix

Ms.

First Name Last Name

Sheila Hill

Title

Project Manager

Organization Name

Lake Mitchell Sewer Authority

Phone Type Number Extension

Business 2317750155

Email

operationsoffice@lakemithcellsewer.com

Fax

NONE PROVIDED

Address

3161 S LAKE MITCHELL DR

CADILLAC, MI 49601

United States

Do you have any additional comments or uploads you would like to provide?

YES

Additional Information

E coli tests results won't be available until 8/13/21

Upload addition information, as needed.

NONE PROVIDED

Comment

NONE PROVIDED

Status History

	User	Processing Status
8/12/2021 12:06:32 PM	Sheila Hill	Draft
8/12/2021 1:50:24 PM	Sheila Hill	Submitting

8/16/2021 4:05:35 PM Page 4 of 5

	User	Processing Status
8/12/2021 1:50:32 PM	Sheila Hill	Submitted

8/16/2021 4:05:35 PM Page 5 of 5